

# WILL YOUR SHUTTERS - AND YOU - MAKE IT?

## A 5.1 FURNACE TEMPERATURE AS3959-2009, AS1530.8.2




FIGURE A 5.1: Furnace Temperatures vs Time

**WHAT'S THE RIGHT CHOICE  
FOR YOU AND YOUR HOME?**

With the introduction of the new Bushfire Standards the higher level of BAL-FZ recognised fire temperatures greater than the previous Standard.

When the Standard was adopted, no window products made it through the new test requirements. The Sonnenschutz BAL-FZ Shade&Shield Shutter system was developed and tested to meet the rigours of this new Australian Standard, to provide a safe option for building in high risk areas.

The system has been used by the NSW RFS and SES in their headquarters at North Warrroonga – in recognition that this is the only shutter system that has passed the test AS3959-2009, AS1530.8.2 for Flame Zone.

Many products have tried to pass this test and failed, or have been certified by an engineer, but never tested to the Standard.

Why would you invest to build the rest of your home to meet the requirements of AS3959-2009, and use an unproven window protection system?



For further information:

t: 03 5368 2645

e: [info@sonnenschutz.com.au](mailto:info@sonnenschutz.com.au)

[www.sonnenschutz.com.au](http://www.sonnenschutz.com.au)